



**INTERNATIONAL ROAD DYNAMICS INC.**

702 - 43rd Street East, Saskatoon, SK, Canada,

Phone: (306) 653-6600 Fax: (306) 242-5599

## **- Site Service Report -**

Date: June 10, 2009

**IRD SO.: 10407 C**

**IRD Contract No.:**

**From: Bryan Knight**

**To: Greg Felsing**

**Project Name/Location: LTTP site Buckeye, AZ**

**Service Date(s): 25 October 2007**

**Job Description: Install new BP Clamp Bars**

- Removed both Bending Plates and Shims.
- Cleaned and vacuumed the frames prior to BP reinstall.
- Doug Pratt performed a cursory inspection for leveling and BP wear condition.
- Reinstalled original shims with no changes made to leveling.
- Installed new BP clamp bars with thicker orange rubber seal.
- Verified BP's are working properly prior to leaving site.

**Work Remaining: Scheduled return for Calibration**

**Parts Used: Four (4) new BP Clamp Bars**

**Mileage / Travel Time: Total Travel: 4 hrs Total Onsite: 5.25 hrs**

**Notes:**

### **Action Items:**

<b>Item</b>	<b>Action Required</b>	<b>Ownership</b>
1.		
2.		
3.		
4.		